








James
JJ Waste & Demolition Services Ltd
EMAIL: jjwaste@hotmail.com

History ID : 326

CUSTOMER DETAILS	
Chassis Number	ys2p8x40005418885
Machine/Vehicle Name/Identifier	Scania 410
Address	, Denham, Buckinghamshire, UB9
Date / time	06/November/2024
Driver/Operator	
Client	JJ
Project	Hook
Inspection Carried Out By	

Daily checks	Details good	Other Comments	Images
fuel/oil leaks	working order		
battery security conditions	looks good		
tyres/wheel and fixings	good		
spray suspension	need attention		
vehicle height	15.9		
mirrors/glass/visibility	need a clean		
cab conditions	Needs Tlc		
air build up or leaks	good working order		
lights	good working order		
reflectors and markers	good working order		
indicator lights	good working order		
wipers	worn but ok		